

Accutemp has released a kit; P/N RK935 (see Fig B) that allows the Gast Pump Model 74R142-V122-H203X (see Fig A) to be rebuilt in the field as long as the electric motor is still functional. The kit contains a new cylinder cup, cylinder, leaf valves and easy to follow instructions.

The bench time to install the kit is less than 30 minutes.

Orders can be placed by phone 800-480-0415 or fax 260-493-8914. Please provide a PO number when ordering.

If you have any questions concerning this memo contact us at 800-480-0415 or by email at service@accutemp.net.



Gast Pump Model 74R142-V122-H203X Fig A



RK935 Rebuild kit Fig B